

FLUOR DANIEL

RECORD OF TELEPHONE CONVERSATION

FROM: Tom Casabonne DATE: 4-5-93
LOCATION: Irvine, X6657 TIME: 9:00 am
TO: Ken Smith (214) 205-2713 P.O. NO. _____
LOCATION: Garland, TX OTHER REF. Site access

Mr. Smith said that when a difference occurs between his records and the Dallas County Tax Office records regarding site ownership, he would defer to the county's records. The county had shown different ownership on sites such as Quail Creek, where Mr. Smith's records indicated owners such as Sunbelt Federal Savings. The county shows other owners (refer to my two previous telephone logs with Ken Smith and the County Tax Office). Mr. Smith also said to send letters to him when we request site access. He will also escort Fluor Daniel around the sites when a site visit is made.

He said that the 13 wells around the current site (Castle Drive) are 35 to 50 feet deep. The site has a clay liner which is a minimum of 3 ft. thick, and the state requires soil caps on closed landfills. He also has analytical data from the well monitoring program, although it was too much information for him to fax. All of the other sites in the area just have a natural clay liner, with approximately 2 ft. of topsoil for a cap. At the East Miller Road Site, Mr. Smith said that the Lakeview subdivision is not on the old site—it is approximately 100 ft. south of the site. The City of Dallas owns the land east of the East Miller Road site because it falls within the "take line" for Lake Ray Hubbard.

liners